
















- A x2  350mm
- B x6 
- C x4  16x12
- D x4  M6x8
- E x6   $\phi 20$
- F x26  16x12
- G x24  M6 7x34
- H x42  8x30







- I x28  M6 8x12
- J x30  3.5x16
- K x20  3.5x16
- L x2 
- M x8  M7x50
- N x1  M4
- O x2  M6 7x34
- P x1  100x80
- Q x6   $\phi 8,5mm$
- R x2 
- S x1   $\phi 60$




Номер упаковки	Деталь	Размер (ДхШхВ)	Кол.
1	1	1200x430x16	1
	6	410x88x16	2
	14	405x167x16	2
	3	372x90x16	1
	16	386x167x16	1
	5,9	350x65x16	4
	8	322x51x16	2
	4	1166x581x16	1
	13	1166x74x16	1
	2,11	581x90x16	2
	15	565x74x25	1
	17	565x74x25	1
	12	380x74x16	2
	7	357x336x4	2
	A-S	570x110x60	1
2	10	800x640x430	2

LOFT 1200x600x750 Арт.4003605H




4

- 3** -1
- 4** -1
- A** -2
- C** -4
- F** -2
- H** -16
- M** -8
- N** -1
- O** -2




6

Используйте отвёртку с магнитным наконечником



- 10** -2
- K** -20
- S** -1

5



x2

Вставить ящики в направляющие до щелчка.

7

